


# Calibrating your ActivBoard



01. **Computer** - Click on the 'ActivManager' icon in the menu bar.
02. Select 'Calibrate'.
03. Follow the on-screen instructions.
04. **ActivBoard** - Hover the pen over the lit flame in the top left hand corner of the board, don't tap the pen.
05. Follow the on-screen instructions.

